

Oil Field Environmental Incident Summary

Incident: 20151221083831 **Date/Time of Notice:** 12/21/2015 08:38

Responsible Party: OXY USA INC.

Well Operator: OXY USA INC.

Well Name: DENNIS KADRMAS 2-9-4H-143-96

Field Name: FAYETTE

Well File #: 22677

Date Incident: 12/20/2015 **Time Incident:** 07:00

Facility ID Number:

County: DUNN

Twp: 143

Rng: 96

Sec: 9

Qtr:

Location Description:

Submitted By: Dustin Tescher

Received By:

Contact Person: Dustin Tescher
PO BOX 2000
DICKINSON, ND 58601

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.3 Mile

Distance Nearest Water Well: 1.3 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	9	Barrels	9	barrels

Brine

Other

Description of Other Released Contaminant:

crude oil

Inspected:

Written Report Received: 3/9/2016

Clean Up Concluded: 12/22/2015

Risk Evaluation:

contaminated surface material

Areal Extent:

An are 90 feet wide and 1000 ft long was sprayed with oil

Potential Environmental Impacts:

contaminated surface material and possible runoff

Action Taken or Planned:

Well was shut down to stop the release. All affected snow/soil was removed and all affected vegetation will be cut and collected.

Wastes Disposal Location: Recovered snow and fluids will be taken to Cabernet SWD. Any recovered solids will be taken to appropriate disposal TBD.

Agencies Involved:**Updates**

Date: 12/21/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release did not remain on the well pad. Further followup is necessary.

Date: 12/29/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:00. 12 degrees F, light snow, NW wind 0-5 mph. Observed site and took photos. It appeared that the heater/treater, located on the east side of the well pad, had a malfunction and sprayed oil towards the E/SE on to pastureland. The approximate area of impact is as described in the report.

Due to approximately 2-3 inches of snow covering the ground, a visual determination of the whole area could not be made. However, the size of the release was determined by an area lacking vegetation where equipment had disturbed the vegetation and some soil.

Further followup will be needed for confirmation samples and/or visual observations in the spring/summer 2016.

Date: 5/17/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 5/17/2016, at 11:47 a.m. Area off location to the east of the treater has been scraped to bare soil. The area is approximately 60 X 50 ft. There is no vegetation growing in this area. I spoke with contact who will be looking at site to determine if it had been reseeded this spring. Further follow-up is required.